

25 YEAR RE-REVIEW

SECRET

19 JAN 63 2238Z

DIRECTOR

ROUTINE

OSA (1-2-3-4-5-6-7-8-9-10-11-12-13-14-15-16)

S/C (17)

TOR: 20 JAN 63 0200Z

IN 63082

0603

1. G-3213/190140Z/342

2. 9/100/27/25

A. 9R/35/0-11-6000/189-10-9-6-2/9L/39/0-11-6000/188-9-12-5-2

B. 38/6/10/150/BUILT-IN

C. 5040/3360/5040/3360/5040

D. 1-190434Z/STBY-190815Z/OFF-190816Z

E. UNKNOWN

3. ALL O.K. LIFE CYCLE COUNTER AT END OF MSN - 98715.

LANDED PRIOR TO RETURN TO

4. 19/0/10

A. P-6 1000/144-14-5-62

B. 32/3E/RED

C. STOPPED

D. N/A

SECRET

GROUP 1
Excluded from automatic
downgrading and
declassification

REPRODUCTION BY OTHER THAN THE ISSUING OFFICE IS PROHIBITED.

Copy No.

25X1

S E C R E T

0603, IN 63082

PAGE TWO

25X1 5. TRACKER FAILED TO METER AFTER SCAN CYCLE COMPLETED. METERING SOLENOID DID NOT ENERGIZE BECAUSE RELAY FAILED. RELAY HAD ONLY APPROX 30 HOURS OF OPERATION.

6. GOOD

7. CLEAR

8. GOOD

9. GOOD

10. NONE

11. NO TURBULENCE. GENERAL WEATHER - CLEAR.

END OF MESSAGE

S E C R E T